	Туре	L #	Hits	Search Text	DBs
1	BRS	L1	323	399/50.ccls.	US- PGPUB; USPAT
2	BRS	L2	437	399/53,55.ccls.	US- PGPUB; USPAT
3	BRS	L3	366	2 not 1	US- PGPUB; USPAT
4	BRS	L4	523	399/66.ccls.	US- PGPUB; USPAT
5	BRS	L5	482	4 not (1 or 2)	US- PGPUB; USPAT
6	BRS	L6	371	399/43,46.ccls.	US- PGPUB; USPAT
7	BRS	L7	295	6 not (1 or 2 or 4)	US- PGPUB; USPAT
8	BRS	L8	363	399/82.ccls.	US- PGPUB; USPAT
9	BRS	L9	347	8 not (1 or 2 or 4 or 6)	US- PGPUB; USPAT
10	BRS	L10	266	399/149,150.ccls.	US- PGPUB; USPAT
11	BRS	L11	233	10 not (1 or 2 or 4 or 6 or 8)	US- PGPUB; USPAT
12	BRS	L12	5130	(stop\$4 or terminat\$3 or cut\$4) with (charg\$3 near2 (bias\$3 or voltage\$1 or potential\$1 or power\$1))	US- PGPUB; USPAT
13	BRS	L13	324	12 and "399"/\$3.ccls.	US- PGPUB; USPAT
14	BRS	L14	234	13 not (1 or 2 or 4 or 6 or 8 or 10)	US- PGPUB; USPAT

	Туре	L #	Hits	Search Text	DBs
15	BRS	L15	10562	(potential\$1 or voltage\$1 or bias\$3) with develop\$4 with (drum\$1 or photosensitive or photoconduct\$3 or (imag\$3 adj1 bearing))	US- PGPUB; USPAT
16	BRS	L16	279	12 and 15	US- PGPUB; USPAT
17	BRS	L17	42	16 not 13	US- PGPUB; USPAT
18	BRS	L18	120	(transfer\$4 near2 (bias\$3 or potential\$1 or voltage\$1 or power\$1)) same 12	US- PGPUB; USPAT
19	BRS	L19	70	18 not (13 or 17)	US- PGPUB; USPAT
20	BRS	L20	0	19 and "399"/\$3.ccls.	US- PGPUB; USPAT
21	BRS	L21	70	19 not 20	US- PGPUB; USPAT
22	BRS	L22	722920	ground\$3	US- PGPUB; USPAT
23	BRS	L23	375	22 same 12	US- PGPUB; USPAT
24	BRS	L24	14	23 and "399"/\$3.ccls.	US- PGPUB; USPAT
25	BRS	L25	361	23 not 24	US- PGPUB; USPAT
26	BRS	L26	351	25 not (13 or 17 or 19)	US- PGPUB; USPAT
27	BRS	L27	1452	I — — — — — — — — — — — — — — — —	EPO; JPO

	Type	L#	Hits	Search Text	DBs
28	BRS	L28	108893	G03g015/02.ipc. or g03g015/00.ipc. or g03g015/06.ipc. or g03g015/08.ipc. or g03g015/16.ccls.	EPO; JPO
29	BRS	L29	49	27 and 28	EPO; JPO
30	BRS	L30	4024	(potential\$1 or voltage\$1 or bias\$3) with develop\$4 with (drum\$1 or photosensitive or photoconduct\$3 or photorecept\$3 or (imag\$3 adj1 bearing))	EPO; JPO
31	BRS	L31	14	27 and 30	EPO; JPO
32	BRS	L32	2	31 not 29	EPO; JPO
33	BRS	L33	17	(transfer\$4 near2 (bias\$3 or potential\$1 or voltage\$1 or power\$1)) and 27	EPO; JPO
34	BRS	L34	13	33 not (29 or 32)	EPO; JPO